

Photo report

Renovation of the unpaved link road between Ereke and BauBau in the region of North Buton/Sulawesi by using the NovoCrete® technology

- Location: North Buton/Indonesia
- Period of execution: March 2012
- Time needed: 5 days
- Cement: 190 kg/m³ + 2 % NovoCrete
- Milling depth: 30 cm

**AUTARK Energy & Infrastructure
Solutions GmbH & Co. KG**

Brienner Str. 9, D-80333 München, Germany

Phone +49 (0) 89-290 97 286

Fax +49 (0) 89-290 97 446

www.autark-energy.com

moormann@autark-energy.com

Soil stabilisation with NovoCrete®



Butur 2a section 1 19. + 20.03.2012

Photo report: Renovation of a link road in North Buton

page 3



Road marking

Photo report: Renovation of a link road in North Buton

page 4



Transportation of the milling unit

Photo report: Renovation of a link road in North Buton



Distribution of cement bags

Photo report: Renovation of a link road in North Buton



Distribution of cement bags

Photo report: Renovation of a link road in North Buton

page 7



Manually distribution of cement

Photo report: Renovation of a link road in North Buton



Manually distribution of cement

Photo report: Renovation of a link road in North Buton



Spreading of NovoCrete

Photo report: Renovation of a link road in North Buton



Check of spreaded amount of NovoCrete

Photo report: Renovation of a link road in North Buton

page 11



Check of spreaded amount of NovoCrete

Photo report: Renovation of a link road in North Buton

page 12



Milling procedure

Photo report: Renovation of a link road in North Buton



Levelling

Photo report: Renovation of a link road in North Buton



Compaction

Photo report: Renovation of a link road in North Buton



Surface of finished area

Photo report: Renovation of a link road in North Buton



Finished area blocked for traffic

Butur 2a section 1

21. + 22.03.2012

Photo report: Renovation of a link road in North Buton



Spreading of cement

Photo report: Renovation of a link road in North Buton

page 19



Milling procedure

Photo report: Renovation of a link road in North Buton

page 20



Milling procedure

Photo report: Renovation of a link road in North Buton

page 21



Situation after the milling procedure

Photo report: Renovation of a link road in North Buton



Compaction

Photo report: Renovation of a link road in North Buton

page 23



Levelling

Photo report: Renovation of a link road in North Buton



Finished area

Photo report: Renovation of a link road in North Buton



Finished area blocked for traffic

Photo report: Renovation of a link road in North Buton

page 26



Finished area blocked for traffic

Butur 2a section 2 21. + 22.03.2012

Photo report: Renovation of a link road in North Buton



Preparation of the rough level

Photo report: Renovation of a link road in North Buton

page 29



Road marking

Photo report: Renovation of a link road in North Buton

page 30



Distribution of cement bags

Photo report: Renovation of a link road in North Buton



Distribution of cement bags

Photo report: Renovation of a link road in North Buton

page 32



Spreading of NovoCrete

Photo report: Renovation of a link road in North Buton

page 33



Milling procedure

Photo report: Renovation of a link road in North Buton

page 34



Compaction

Photo report: Renovation of a link road in North Buton

page 35



Irrigation of the surface

Photo report: Renovation of a link road in North Buton



Surface of finished area

Photo report: Renovation of a link road in North Buton



Finished area blocked for traffic

Butur 2a section 3 24.03.2012

Photo report: Renovation of a link road in North Buton

page 39



Transportation of the milling unit

Photo report: Renovation of a link road in North Buton



Distribution of cement bags

Photo report: Renovation of a link road in North Buton



Distribution of cement bags

Photo report: Renovation of a link road in North Buton



Spreading of NovoCrete

Photo report: Renovation of a link road in North Buton

page 43



Milling procedure

Photo report: Renovation of a link road in North Buton

page 44



Milling procedure

Photo report: Renovation of a link road in North Buton

page 45



Compaction

Photo report: Renovation of a link road in North Buton

page 46



Levelling

Photo report: Renovation of a link road in North Buton

page 47



Finished area blocked for traffic

Photo report: Renovation of a link road in North Buton



Finished area blocked for traffic

Photo report: Renovation of a link road in North Buton



Close-up of the finished surface